

A
 $S=4,4\text{mA/V}$
 $\mu=18$
 $R_i=4,1\text{k}$
 $P_a=\text{max.}5,5\text{W}$

B
 $S=2\text{mA/V}$
 $\mu=20$
 $R_i=1\text{k}$
 $P_a=\text{max.}1,25\text{W}$

