

$S_p = 6,2 \text{ mA/V}$   
 $R_i = 300 \text{ k}$   
 $P_a = \text{max. } 2 \text{ W}$

$S_T = 3,3 \text{ mA/V}$   
 $R_i = 5,75 \text{ k}$   
 $\mu = 19$   
 $P_a = \text{max. } 2,5 \text{ W}$

